



PHOTOGRAPHS FOR


Rochelle Municipal Utilities	June 27, 2012
P.O. Box 456	Investigation of Building Wall Joints
Rochelle, Illinois 61068	WHA#1178D11


Photograph #1	Comments
 A vertical photograph showing a close-up of a concrete wall joint. A dark, narrow crack runs vertically down the center of the joint, separating two sections of light-colored, textured concrete.	Photograph of general condition of all existing building joints.

Photograph #2	Comments
 A vertical photograph showing a close-up of a concrete wall joint. A dark, narrow crack runs vertically down the center of the joint. A yellow measuring tape is placed horizontally across the bottom of the joint, showing markings for inches and feet. The tape indicates the crack is approximately 2.5 feet wide at the bottom.	Photograph of general condition of all existing building joints.

PHOTOGRAPHS FOR

Rochelle Municipal Utilities	June 27, 2012
P.O. Box 456	Investigation of Building Wall Joints
Rochelle, Illinois 61068	WHA#1178D11

Photograph #3	Comments
	Photograph of general condition of at existing wall penetrations.

Photograph #4	Comments
	Photograph of general condition of at existing wall penetrations.